

SPEEDDIAL

WARNING

NEVER ATTEMPT TO CHANGE SPEEDS WHEN THE MOTOR IS TURNED OFF.

The Shopsmith Speeddial makes speed selection easy. Settings for most common operations are engraved on the dial. For more detailed operational speed information refer to the speed chart.

Turning the dial clockwise increases the speed and counter-clockwise decreases the speed. Make it a habit to turn the speeddial to “slow” before shutting off the motor for position or accessory change unless the next operation requires the same or a higher speed. After the accessory is attached to the spindle turn on the motor and turn the speeddial to the RPM required. Turn the speeddial to slow before turning off the motor when finished using the Shopsmith.

Turning the speeddial with the motor off will damage the mechanism. Never force the speeddial, it should turn with little effort. If the speeddial becomes hard to turn service is required.